

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

FI808  
West  
> 1  
1.121 mi.  
5921 ft.

MAHOLE 71173  
33RD ST & NEPTUNE AVE  
BROOKLYN, NY

NY Spills S103829827  
N/A

Site 2 of 5 in cluster FI

Relative:  
Higher

Actual:  
0 ft.

SPILLS:

Name: MAHOLE 71173  
Address: 33RD ST & NEPTUNE AVE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 9900194 / 1999-05-13  
Facility ID: 9900194  
Facility Type: ER  
DER Facility ID: 145995  
Site ID: 173538  
DEC Region: 2  
Spill Cause: Unknown  
Spill Class: C4

SWIS: 2401  
Spill Date: 1999-04-06  
Investigator: CAENGELH  
Referred To: Not reported  
Reported to Dept: 1999-04-06  
CID: 322  
Water Affected: Not reported  
Spill Source: Unknown  
Spill Notifier: Affected Persons  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 1999-04-06  
Spill Record Last Update: 2000-06-15  
Spiller Name: UNKNOWN  
Spiller Company: Unknown  
Spiller Address: UNKNOWN  
Spiller Company: 999  
Contact Name: Not reported  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was  
ENGELHARDT DEC Inspector Notes: 5/12/99: 16:14-- emailed ERT's for  
copy of e2mis report. Con ed e2mis notes: Found undiaperble sheen on  
100 gallons of water in mh. <1.00ppm CLeaup complete and tag  
removed.a "

Remarks: "UNDIAPERALBE SHEEN OF UNK FLUID ON 100 GAL OF WATER - CONTAINED IN  
MANHOLE - CON ED 124074 - SAMPLE TAKEN CLEAN UP PENDING RESULTS "

All Materials:

Site ID: 173538  
Operable Unit ID: 1078987  
Operable Unit: 01  
Material ID: 307336  
Material Code: 0064A  
Material Name: unknown material  
Case No.: Not reported  
Material FA: Other  
Quantity: .00  
Units: G  
Recovered: .00

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Oxygenate:

Not reported